Montana Board of Oil and Gas Conservation Environmental Assessment

Operator: Continental Resources, Inc.
Well Name/Number: _Shevlin 1-20H
Location: NW NE Section 20 T23N R55E
County: Richland , MT; Field (or Wildcat) W/C (Bakken Horizontal)
· · · · · · · · · · · · · · · · · · ·
A1
Air Quality
(possible concerns)
Long drilling time: No, long time drilling, will require about 30 to 40 days drilling time.
Unusually deep drilling (high horsepower rig): No, will utilize a triple derrick drilling rig to drill a
single lateral Bakken Formation horizontal well, 19,711'MD/10,038'TVD.
Possible H2S gas production: Slight chance of H2S gas.
In/near Class I air quality area: No Class I air quality area nearby. Air quality permit for floring (venting (if productive): Year DEO air quality permit required under
Air quality permit for flaring/venting (if productive): Yes, DEQ air quality permit required under
rule 75-2-211. Mitigation:
_X Air quality permit (AQB review)
Gas plants/pipelines available for sour gas
Special equipment/procedures requirements
Other:
Comments: No special concerns – using triple rig to drill a single lateral Bakken
Formation horizontal well, 19,711'MD/10,038'TVD
Water Quality
(possible concerns)
Salt/oil based mud: Yes, oil based invert drilling fluids to drill the intermediate casing string
hole and saltwater/brine fluid system to drill the horizontal lateral. Freshwater and freshwater
mud system to be used to drill the surface hole.
High water table: No high water table anticipated at this location.
Surface drainage leads to live water:Yes, nearest drainage is an unnamed ephemeral
tributary drainage to East Fork Fox Creek, about 1/32 of a mile to the north from this location.
Water well contamination: No, closest water wells are 1 mile and further in any direction from
this location. Surface hole will be drilled with freshwater and freshwater drilling fluids. Surface
casing will be set at 1761' and cemented to surface.
Porous/permeable soils: No, silty sandy clay soils.
Class I stream drainage: No Class I stream drainages in the area of review.
Mitigation:
X Lined reserve pit
X Adequate surface casing
Berms/dykes, re-routed drainage
Closed mud system
Off-site disposal of solids/liquids (in approved facility)
Other: Comments:1761' of surface casing cemented to surface adequate
to protect freshwater zones and will cover the base of the Fox Hills Formation.
to proteot meanwater zones and will cover the base of the rox rillis ronnation.

Soils/Vegetation/Land Use

(possible concerns)
Steam crossings: None anticipated, crossing an unnamed ephemeral drainages only
High erosion potential: No, moderate cut, up to 10.1' and moderate fill, up to 17.4', required.
Loss of soil productivity: No, location will be restored after drilling if unproductive. If productive,
unused portion of this drilling location will be restored.
Unusually large wellsite: No, large wellsite, 500'X270' location size required.
Damage to improvements: Slight, surface use scrub land surrounded by cultivated fields.
Conflict with existing land use/valuesSlight
Mitigation
Avoid improvements (topographic tolerance)
Exception location requested
X Stockpile topsoil
Stream Crossing Permit (other agency review)
X_Reclaim unused part of wellsite if productive
Special construction methods to enhance reclamation
Other
Comments:Access will be over existing county road, #328 and section line roads. About
2391' of new access road will be built into this location from the east section line. Cuttings will
be buried in the lined reserve pit. Oil based invert drilling fluids will be recycled. Reserve pit
fluids and completion fluids will trucked to a commercial SWD well. No special concerns.
Health Hazards/Noise
(possible concerns)
Proximity to public facilities/residences: Closest residences are about 5/8 of a mile to the
northwest and 1.25 miles to the west northwest from this location. The town of Lambert,
Montana is about 5 miles to the southeast from this location.
Possibility of H2S: Slight chance.
Size of rig/length of drilling time: Triple drilling rig/short 30 to 40 days drilling time required.
Mitigation:
_X_Proper BOP equipment
Topographic sound barriers
H2S contingency and/or evacuation plan
Special equipment/procedures requirements
Other:
Comments:Adequate surface casing cemented to surface and operational BOPs
should mitigate any problems. No concerns.

Wildlife/recreation
(possible concerns)
Proximity to sensitive wildlife areas (DFWP identified): Fox Lake State Game Management Area
is about 4 miles to the south.
Proximity to recreation sites:None identified.
Creation of new access to wildlife habitat: No
Conflict with game range/refuge management: No
Threatened or endangered Species: Species identified as threatened by the USFWS are
Pallid Sturgeon, Interior Lease Tern, Piping Plover and Whooping Crane. Species listed as
candidate species are the Greater Sage Grouse and Sprague's Pipit. NH tracker website for
this Township and Range lists no species of concern.

Mitigation:
Avoidance (topographic tolerance/exception)
Other agency review (DFWP, federal agencies, DSL)
Screening/fencing of pits, drillsite
Other:
Comments: Private surface lands. There maybe species of concern that maybe
impacted by this wellsite. We ask the operator to consult with the surface owner as to what he
would like done, if a species of concern is discovered at this location. The Board of Oil & Gas
has no jurisdiction over private surface lands.
nas no junsuiction over private surface lands.
Historical/Cultural/Paleontological
(possible concerns)
Proximity to known sites None identified.
Mitigation
avoidance (topographic tolerance, location exception)
other agency review (SHPO, DSL, federal agencies)
Other:
Comments: On private surface lands. There maybe possible
historical/cultural/paleontological sites that maybe impacted by this wellsite. We ask the
operator to consult with the surface owner as to his desires to preserve these sites or not, if they
are found during construction of the wellsite. The Board of Oil & Gas has no jurisdiction over
private surface lands.
<u></u>
Social/Economic
(possible concerns)
Substantial effect on tax base
Create demand for new governmental services
Population increase or relocation
Comments: No concerns.
Demonto on Charlet Concerns for this site
Remarks or Special Concerns for this site
Will drill a single lateral Bakken Formation horizontal well, 19,711'MD/10,038'TVD. No special
concerns.
Summary: Evaluation of Impacts and Cumulative effects
No simulficant languateur insurate associated associated associated associated associated will associated asso
No significant long term impacts expected, some short term impacts will occur.
I conclude that the approval of the subject Notice of Intent to Drill (does/does not) constitute a
major action of state government significantly affecting the quality of the human environment,
and (does/does not) require the preparation of an environmental impact statement.
Prepared by (BOGC):_/s/Steven Sasaki
(title:) Chief Field Inspector

Date: November 14, 2011
Other Persons Contacted:
Montana Bureau of Mines and Geology, GWIC website
(Name and Agency) Water wells in Richland County
(subject discussed) November 14, 2011
(date)
US Fish and Wildlife, Region 6 website (Name and Agency) ENDANGERED, THREATENED, PROPOSED AND CANDIDATE SPECIES MONTANA COUNTIES, Richland County (subject discussed)
_November 14, 2011
Montana Natural Heritage Program Website (FWP) (Name and Agency) Heritage State Rank= S1, S2, S3, T23N R55E (subject discussed)
November 14, 2011 (date)
If location was inspected before permit approval: Inspection date: Inspector:
Others present during inspection: